



Aeroflex (MACOM Technology Solutions)

MACP-009596-CA0160

Zenbakiaren zenbakia: MACP-009596-CA0160

Fabrikatzaileak / Marka: Aeroflex (MACOM Technology Solutions)

Produktuaren Deskribapena: RF DIR COUPLER 5MHZ-1GHZ SM22

Fitxak: [PDF MACP-009596-CA0160.pdf](#)

RoHS egoera: Lead free / RoHS betez

Stock egoera: 27221 pcs stock

Ontziatik aurrera: Hong Kong

Bidalketa Bidea: DHL/Fedex/TNT/UPS/EMS

Solutions)



Irudia ordezkaritza izan daiteke. Ikusi produktuaren zehetasunetarako zehaztapenak.

AURREKONTUEN ESKAERA

MACP-009596-CA0160ren zehaztapenak

ZENBAKIAREN ZENBAKIA	MACP-009596-CA0160
FABRIKATZAILEA	Aeroflex (MACOM Technology Solutions)
DESKRIBAPENA	RF DIR COUPLER 5MHZ-1GHZ SM22
LEAD FREE STATUS / ROHS EGOERA	Lead free / RoHS betez
KOPURUA ESKURAGARRI	27221 pcs
DATUEN FITXA	PDF MACP-009596-CA0160.pdf
HORNITZAILEEN GAILUEN PAKETEA	SM-22
SERIES	-
ITZULERAKO GALERA	-16dB
ENERGIA - MAX	-
PACKAGING	Cut Tape (CT)
PAKETE / KASUA	6-SMD Module
BESTE IZENAK	1465-1321-1
HEZETASUNAREN SENTIKORTASUN MAILA (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS EGOERA	Lead free / RoHS Compliant
ISOLAMENDUA	-
TXERTATZE GALERA	-
FREQUENCY	5MHz ~ 1GHz
DESKRIBAPEN ZEHATZA	RF Directional Coupler 5MHz ~ 1GHz 10dB 6-SMD Module
AKOPLAMENDU FAKTOREA	10dB
COUPLER TYPE	Standard
ESKAERAK	-

Erlazionatutako etiketak

Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	MACP-009596-CA0160 banatzailea	MACP-009596-CA0160 hornitzailea
MACP-009596-CA0160 Prezioa	MACP-009596-CA0160 irudiak	MACP-009596-CA0160 Irudia
MACP-009596-CA0160 PDF fitxa	MACP-009596-CA0160 Deskargatu fitxa	MACP-009596-CA0160 Datasheet
MACP-009596-CA0160 Stock	Erosi MACP-009596-CA0160	Erosi Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160
Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	Aeroflex (MACOM Technology Solutions) hornitzailea	Aeroflex (MACOM Technology Solutions) banatzailea
Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	Aeroflex Circuit Technology MACP-009596-CA0160	Aeroflex MACP-009596-CA0160
Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160	Aeroflex Metelics, Division of MACOM MACP-009596-CA0160	M/A-Com Technology Solutions MACP-009596-CA0160
Metelics (MACOM Technology Solutions) MACP-009596-CA0160	MACOM Technology Solutions MACP-009596-CA0160	

Produktu erlazionatuak

<p>MACP-008125-CK07TB fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: EVAL BOARD FOR MACP-008125-CK07F Stockean: 555 pcs</p> <p>RFQ</p>	<p>MACP-010507-CH0160 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-300MHZ 5SMD Stockean: 75562 pcs</p> <p>RFQ</p>
<p>MACP-008125-CK07F0 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1GHZ SM127 Stockean: 3506 pcs</p> <p>RFQ</p>	<p>MACP-009596-CA01TB fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: EVAL BOARD FOR MACP-009596-CA016 Stockean: 485 pcs</p> <p>RFQ</p>
<p>MACP-007727-CI07B0 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ SM123 Stockean: 55152 pcs</p> <p>RFQ</p>	<p>MACP-009730-C60370 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ MOD Stockean: 68058 pcs</p> <p>RFQ</p>
<p>MACH102-8TP-R fabrikatzaileak: Belden's Hirschmann deskribapena: NETWORK SWITCH-MANAGED 8 PORT Stockean: 60 pcs</p> <p>RFQ</p>	<p>MACP-010561-000000 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 2GHZ-6GHZ 6TDFN Stockean: 4788 pcs</p> <p>RFQ</p>
<p>MACP-009011-C80370 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 29238 pcs</p> <p>RFQ</p>	<p>MACP-010414-CA0370 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 103049 pcs</p> <p>RFQ</p>
<p>MACP-007727-CI07TB fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: EVAL BOARD FOR MACP-007727-CI07B Stockean: 583 pcs</p> <p>RFQ</p>	<p>MACP-010250-C808A0 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ MOD Stockean: 114443 pcs</p> <p>RFQ</p>

