



Aeroflex (MACOM Technology Solutions)

MACP-011015

Zenbakiaren zenbakia:

Fabrikatzaileak / Marka:

Produktuaren Deskribapena

Fitxak:

RoHS egoera

Stock egoera

Ontziatik aurrera

Bidalketa Bidea

MACP-011015

Aeroflex (MACOM Technology Solutions)

RF DIR COUPLR 40MHZ-1.25GHZ 5SMD

MACP-011015.pdf

Lead free / RoHS betez

24969 pcs stock

Hong Kong

DHL/Fedex/TNT/UPS/EMS

Solutions)



Irudia ordezkari izan daiteke. Ikusi produktuaren xehetasunetarako zehaztapenak.

MACP-011015ren zehaztapenak

ZENBAKIAREN ZENBAKIA	MACP-011015
FABRIKATZAILEA	Aeroflex (MACOM Technology Solutions)
DESKRIBAPENA	RF DIR COUPLR 40MHZ-1.25GHZ 5SMD
LEAD FREE STATUS / ROHS EGOERA	Lead free / RoHS betez
KOPURUA ESKURAGARRI	24969 pcs
DATUEN FITXA	MACP-011015.pdf
HORNITZAILEEN GAILUEN PAKETEA	5-SMD
SERIES	-
ITZULERAKO GALERA	30dB
ENERGIA - MAX	250mW
PACKAGING	Cut Tape (CT)
PAKETE / KASUA	5-SMD Module
BESTE IZENAK	1465-1711-1
HEZETASUNAREN SENTIKORTASUN MAILA (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS EGOERA	Lead free / RoHS Compliant
ISOLAMENDUA	-
TXERTATZE GALERA	1.9dB
FREQUENCY	40MHz ~ 1.25GHz
DESKRIBAPEN ZEHATZA	RF Directional Coupler General Purpose 40MHz ~ 1.25GHz 8dB 250mW 5-SMD Module
AKOPLAMENDU FAKTOREA	8dB
COUPLER TYPE	Standard
ESKAERAK	General Purpose

Erlazionatutako etiketak

Aeroflex (MACOM Technology Solutions) MACP-011015	MACP-011015 banatzailea	MACP-011015 hornitzailea
MACP-011015 Prezioa	MACP-011015 irudiak	MACP-011015 Irudia
MACP-011015 PDF fitxa	MACP-011015 Deskargatu fitxa	MACP-011015 Datasheet
MACP-011015 Stock	Erosi MACP-011015	Erosi Aeroflex (MACOM Technology Solutions) MACP-011015
Aeroflex (MACOM Technology Solutions) MACP-011015	Aeroflex (MACOM Technology Solutions) hornitzailea	Aeroflex (MACOM Technology Solutions) banatzailea
Aeroflex (MACOM Technology Solutions) MACP-011015	Aeroflex Circuit Technology MACP-011015	Aeroflex MACP-011015
Aeroflex (MACOM Technology Solutions) MACP-011015	Aeroflex Metelics, Division of MACOM MACP-011015	M/A-Com Technology Solutions MACP-011015
Metelics (MACOM Technology Solutions) MACP-011015	MACOM Technology Solutions MACP-011015	

Produktu erlazioatuak

<p>MACP-011010 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 69745 pcs</p> <p>RFQ</p>	<p>MACP-010563-000000 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 10GHZ-30GHZ 6TDFN Stockean: 6556 pcs</p> <p>RFQ</p>
<p>MACP-011035 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 31816 pcs</p> <p>RFQ</p>	<p>MACP-010563-TR1000 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 10GHZ-30GHZ 6TDFN Stockean: 4446 pcs</p> <p>RFQ</p>
<p>MACP-011038 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 5028 pcs</p> <p>RFQ</p>	<p>MACP-011013 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Stockean: 75305 pcs</p> <p>RFQ</p>
<p>MACP-010563-001SMB fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: EVAL BOARD FOR MACP-010563-TR100 Stockean: 4608 pcs</p> <p>RFQ</p>	<p>MACP-011034 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 34659 pcs</p> <p>RFQ</p>
<p>MACP-011033 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 34032 pcs</p> <p>RFQ</p>	<p>MACP-011014 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Stockean: 34558 pcs</p> <p>RFQ</p>
<p>MACP-011032 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 33983 pcs</p> <p>RFQ</p>	<p>MACP-011036 fabrikatzaileak: Aeroflex (MACOM Technology Solutions) deskribapena: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Stockean: 4034 pcs</p> <p>RFQ</p>

